Head Office: Plot. No. 1372, Behind Shivaji Garden, Kanherewadi, Nashik- 422001



ROAD ROUGHNESS TEST

As per IRC: SP:16-2019

INSTRUMENT AVAILABLE

- Fifth Wheel Bump Integrator
- Car Axle Mounted Bump Integrator
- Network Survey Vehicle

SERVICES OFFERED

- Roughness DataCollection
- Data Analysis
- **❖ NABL Reporting**

WHY CIVILTECH

- CRRI Calibrated Equipment
- NABL Certified report
- Higher Accuracy
- Latest Technology
- Professional Technical Team



mail: highwaytest@civiltechindia.com civiltechindia@gmail.com +9188886116777

